



ANCHOR AUTO BODY & FRAME
 1028 W EVELYN AVE, SUNNYVALE, CA 94086-5741
 Office: (408) 737-8673
 Fax: (408) 720-8343
 Frontdesk@anchorauto.com
 EPA: CAR00161877 Bar ID: AFf216609 Tax ID: 770571989

Estimate ID
 11445214
 Original
 Claim Number
 CAPA-0194666600102

Owner
ANDREW SHARP
 212 THOMPSON SQ
 MOUNTAIN VIEW, CA 94043
 (650) 906-9448 (Mobile)
 andy@absharp.com

Insured
ANDREW SHARP

Appraiser
Danny Vega
 danny@anchorauto.com

Classification
Drive In

MERCURY INSURANCE GROUP

Loss Type Collision	Claim Number CAPA-0194666600102	Policy Number 040105130064925	Adjuster Elisa Galang (888) 263-7287+27608 (Work)
Deductible 500.00 - Not Waived	Reported Date 08/30/2022	Loss Date 08/26/2022	Inspection Site ANCHOR AUTO BODY 1028 W EVELYN AVE SUNNYVALE, CA 94086-5741

Repair Facility
ANCHOR AUTO BODY & FRAME
 1028 W EVELYN AVE
 SUNNYVALE, CA 94086-5741

2005 Audi S4 Avant 4 Door Wagon 4.2L 8 Cyl Gas Injected 6 Speed Auto Trans AWD

License CA-5LWC422	VIN WAUXL68E55A077180	Drivable Yes	Odometer 145679
Production Date 08/2004	Mitchell Service Code 910215		

Primary Point of Impact
Left Front Corner (11)

Prior Damage Notes
rear cover damaged*hood rock chips.**prior paint work*

Options

Air Conditioning	All Wheel Drive	Alum/Alloy Wheels	AM-FM Stereo	Anti-Lock Brake Sys. (ABS)
Auto Air Condition	Automatic Transmission	Cassette Player	CD Player	CD Player (Multi)
Cruise Control	Driver Seat With Power Lumbar Support	Driver-Front Air Bag	Dual A/C	Electric Defogger
Electronic Stability Control	First Row Bucket Seat	Fog Lights	Front Seats With Power Lumbar Support	Genuine Wood Trim

Heated Mirror	High Intensity Discharge Headlights	Keyless Entry System	Leather Seats	Leather Steering Wheel
Left-Curtain Air Bag	Passenger-Front Air Bag	Power Door Locks	Power Driver Seat	Power Passenger Seat
Power Remote Mirror	Power Steering	Power Windows	Premium Sound Sys.	Rear Bench Seat
Second Row Side Airbag With Head Protection Trip Computer	Side Airbags	Theft Deterrent Sys.	Tilt Steering Wheel	Traction Control/Electronic

ANDREW SHARP | 2005 Audi S4 Avant

Parts Profile
CARS - Nor Cal - Gilroy_1

Parts Profile Version
10.0

Line #	Description	LABOR				PART				
		Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
Front Bumper										
1	002533 Frt Bumper Cover	Remove / Replace	Body	2.6#	2.6	Remanufactured	8E0807103T GRU	1	\$687.00	Yes
2	900501 *oem Discontinued by the Manufacturer.									
3	AUTO Frt Bumper Cover	Refinish Only	Refinish	1.9 C	1.9					
4	002534 Frt Bumper Tow Hook Cover	Remove / Replace	Body	INC*	0.0	New	8E0 807 241 B GRU	1	\$88.33	Yes
5	900501 *left side									
6	002539 Frt Bumper License Plate Bracket	Remove / Replace	Body	INC	0.2	New	8E0 807 285 F 3FZ	1	d\$161.67	Yes
7	900501 Discontinued by the Manufacturer.									
8	002536 Frt Ctr Bumper Grille	Remove / Install	Body	INC#	0.3	Existing				
9	002537 R Frt Otr Bumper Grille	Remove / Install	Body	INC#	0.2	Existing				
10	002538 L Frt Otr Bumper Grille	Remove / Install	Body	INC#	0.2	Existing				
11	900501 note: prior paint overspray									
Grille										
12	002972 Grille	Remove / Replace	Body	0.3#	0.3	Qual Recycled Part	15D01	1	\$125.00	Yes
13	900501 8E0 853 651 D 3SR									
Front Lamps										
14	002975 L Frt Combination Lamp Assembly	Remove / Replace	Body	0.6	0.6	Qual Recycled Part	K00527	1	\$500.00	Yes
15	900510 Line Markup 20.0%								\$100.00	
16	900501 Discontinued by the Manufacturer									
17	001026 R Frt Fog Lamp	Remove / Install	Body	INC#	0.3	Existing				
18	001027 L Frt Fog Lamp	Remove / Install	Body	INC#	0.3	Existing				
Hood										
19	000083 Hood Panel	Repair	Body	1.5*#	1.5	Existing				
20	AUTO Hood Outside	Refinish Only	Refinish	2.6 C	2.6	Existing				
21	900500 Deduction Hood Panel	Access / Inspect	Body*	-0.3*	0.0	Existing				

Line #	Description	LABOR				PART				
		Operation	Type	Total Units	CEG	Type	Number	Qty	Total Price	Tax
Additional Costs & Materials										
22	AUTO Paint/Materials	Additional Cost							\$237.80*	Yes
Additional Operations										
23	AUTO Clear Coat	Additional Operation	Refinish	1.3	0.0				\$0.00	
Special / Manual Entry										
24	900500 COLOR MATCH	Additional Labor	Body*	0.5*	0.0	Existing		1		
25	900500 COVER CAR	Remove / Replace	Body*	0.0*	0.0	Aftermarket New	** QUAL REPL PART	1	\$10.00*	Yes
26	900500 COLOR SAND & POLISH	Additional Labor	Body*	0.6*	0.0	Existing		1		
27	900501 .3 PER PANEL- 1.5 MAX									
28	900500 CORROSION PROTECTION	Remove / Replace	Body*	0.0*	0.0	Aftermarket New	** QUAL REPL PART	1	\$10.00*	Yes
29	900500 FLEX ADDITIVE	Remove / Replace	Body*	0.0*	0.0	Aftermarket New	** QUAL REPL PART	1	\$8.00*	Yes
30	900500 INNER STRUCTURES OPEN	Additional Labor	Body*	0.0*	0.0	Existing		1		
31	900501 PARTS & LABOR SUBJECT TO INVOICE AND AVAILABILITY									

* Judgment Item
T Included in Two Tone Calculation
Labor Note Applies
d Discontinued by Manufacturer
C Included in Clear Coat Calculation
A Included in Clear Coat and Two Tone Calculation
r CEG R&R Time Used for this Labor Operation
[] Verify the part number and price before ordering

Parts Vendors

BAY AREA BUMPERS, INC.
7887 ENTERPRISE DR.
NEWARK CA 94560
(800) 285-2867 (Work)
(510) 505-9010 (Work)

Line	Part #	Total Price
1	8E0807103TGRU	\$687.00

Disclaimer: This estimate has been prepared based on the use of crash parts supplied by a source other than the manufacturer of your motor vehicle. Any warranties applicable to these replacement parts are provided by the manufacturer or distributor of the parts, rather than by the original manufacturer of your vehicle.

Recycled Part Vendors

A-German Auto Parts and Service - SCADA
301 San Jose Ave.
San Jose CA 95125
(408) 993-9711 (Work)
(408) 993-0232 (Work)

Line	Part #	Total Price	Vehicle	Description	VIN
12	15D01	\$125.00	2006 Audi AUDI A4	BRIGHT MOULDING	WAUKF78E76A233941
Supplier Notes: 8E0 010 438 CRACK ONE SIDE OF FRAM					

LKQ-Keystone- Stockton
2041 Navy Drive
Stockton CA 95206
(800) 424-2002 (Work)

Line	Part #	Total Price	Vehicle	Description	VIN
14	K00527	\$500.00	2008 Audi AUDI A4	L.	WAUKF78EX8A113263
Supplier Notes: LH,XENON (HID), W/CURVE LIGHTING (OPT 8Q)					

Disclaimer: Recycled part pricing may represent either actual pricing (the price at which the recycler is willing to sell the part for in its existing condition) or undamaged pricing (the price at which the recycler would sell the part if it was in undamaged condition). If you are unsure, please contact the automotive recycler. Some parts located for this quote may be interchangeable but may not be an exact match. If you are unsure, please contact the automotive recycler.

Estimate Totals

Labor	Units	Rate	Sublet Add'l Amount	Totals
Body Labor	5.8	\$85.00		\$493.00
Refinish Labor	5.8	\$85.00		\$493.00
Total Labor	11.6			\$986.00
			Taxable	\$0.00
			Tax 0.0000%	\$0.00
			Non-Taxable	\$986.00
			Labor Total	\$986.00
Parts	Amount			Totals
Taxable Parts		\$1,590.00		\$1,590.00
			Parts Adjustments	\$112.50
			Tax 9.1250%	\$155.35
			Non-Taxable	\$0.00
			Parts Total	\$1,857.85
Costs	Amount			Totals
Other Additional Costs		\$0.00		\$0.00
Paint Materials		\$237.80		\$237.80
			Taxable	\$237.80
			Tax 9.1250%	\$21.70
			Non-Taxable	\$0.00
Paint Materials Rate: \$41.00			Costs Total	\$259.50
Rate Max: 99.9 units				
Additional Rate: \$0.00				
Gross Totals	Amount			Totals
Gross Total		\$3,103.35		\$3,103.35
			Taxable	\$1,940.30
			Tax	\$177.05
			Non-Taxable	\$986.00
			Gross Total	\$3,103.35
Adjustments	Amount			Totals
Deductible		-\$500.00		-\$500.00

Estimate Totals

**Total Customer
Responsibility**

-\$500.00

Net Estimate Total

\$2,603.35

PARTS PRICES ARE SUBJECT TO INVOICE
OLD PARTS REMOVED FROM CAR WILL BE DISCARDED
UNLESS OTHERWISE INSTRUCTED

Please Take Note

Due to the complexity of auto body repairs i.e. structural, paint and parts availability we can only estimate not guarantee delivery date. With today's automobiles it is necessary to disconnect your vehicle's battery. The result of this will be the loss of your preset radio stations, radio codes and possibly your alarm security code also.

** SPECIAL PARTS NOTICE: ALL CRASH PARTS ON THIS ESTIMATE ARE NEW-OEM (ORIGINAL EQUIPMENT MANUFACTURER) UNLESS OTHERWISE SPECIFIED. PARTS DESCRIBED AS "RECHROMED", "RECORED", OR "REMANUFACTURED" ARE EITHER RECONDITIONED OR REBUILT. PARTS THAT ARE DESCRIBED AS "QUAL REPL PART", AND "QRP CAPA", ARE NON-OEM CRASH PARTS.**

PERSUANT TO CALIFORNIA CODE OF REGULATIONS, TITLE 10, CHAPTER 5, SUBCHAPTER 7.5, SECTION 2695.8 THE INSURER WARRANTS THAT ANY NON-ORIGINAL EQUIPMENT MANUFACTURER PARTS SPECIFIED IN THIS ESTIMATE ARE AT LEAST EQUAL TO THE ORIGINAL EQUIPMENT MANUFACTURER PARTS IN TERMS OF KIND, QUALITY, SAFETY, FIT AND PERFORMANCE

*****Inspection Summary Information*****

Vehicle arrival date? 9-14-22
Was vehicle driven in, towed in or delivered by Road America? DRIVEN IN
Inspection date? 9-14-22
Number of business days to repair? 4DAYS
Was the estimate given to the owner? YES
Is the vehicle a Partial Loss or a Total Loss? PARTIAL LOSS
If Partial Loss, should payment be sent to the facility for repairs? NO

*****CARS Alternate Part Summary*****

Alternate Parts Available? (yes or no)YES
Source: *PARTS SUBJECT TO AVAILABILITY
Phone & Reference (code #)

**Parts Vendors
BAY AREA BUMPERS, INC.**

7887 ENTERPRISE DR.
NEWARK CA 94560
(800) 285-2867 (Work)
(510) 505-9010 (Work)
Line Part # Total Price
1 8E0807103TGRU \$687.00

Recycled Part Vendors
A-German Auto Parts and Service - SCADA
301 San Jose Ave.
San Jose CA 95125
(408) 993-9711 (Work)
(408) 993-0232 (Work)

Line Part # Total Price Vehicle Description VIN
12 15D01 \$125.00 2006 Audi AUDI A4 BRIGHT MOULDING WAUKF78E76A233941

LKQ-Keystone- Stockton
2041 Navy Drive
Stockton CA 95206
(800) 424-2002 (Work)
Line Part # Total Price Vehicle Description VIN
14 K00527 \$500.00 2008 Audi AUDI A4 L. WAUKF78EX8A113263
Supplier Notes: LH,XENON (HID), W/CURVE LIGHTING (OPT 8Q

Disclaimer: For your protection California law requires the following statement to appear on this form. Any person who knowingly presents false or fraudulent information to obtain or amend insurance coverage or to make a claim for the payment of a loss is guilty of a crime and may be subject to fines and confinement in state prison.

Estimate Event Log

Job Created	9/2/2022 04:28 PM
Estimate Started	9/14/2022 08:28 AM
Estimate Printed	9/14/2022 09:14 AM
Estimate Committed	9/14/2022 09:14 AM
Estimate Version	0