Caliber - Mountain View - 1013

177 E Evelyn Ave, Mountain View, CA 94041-1510

Office: (650) 965-1440 Fax: (650) 965-0228

1013Assignments@CaliberCollision.com

Estimate ID 4226906 Original

Claim Number

CAPA-0136633600

101

Owner
ANDREW SHARP
212 THOMPSON SQ
MOUNTAIN VIEW, CA 9404

MOUNTAIN VIEW, CA 94043 (650) 906-9448 (Mobile) andy@absharp.com Insured Appraiser
ANDREW SHARP Crystal Lewis

crystal.lewis@calibercollision.com

Classification None

MERCURY INSURANCE GROUP

Loss Type Claim Number Policy Number Adjuster

Comprehensive CAPA-0136633600101 040105130064925 Michael Mejia

(714) 671-6600 (Work) mimejia@mercuryinsurance.c

om

Deductible Reported Date Loss Date Inspection Site

100.00 - Not Waived 02/04/2020 01/29/2020 CALIBER COLLISION/MOUN

TAIN VIEW

177 E EVELYN AVE MOUNTAIN VIEW, CA

94041-1510

Drivable

2005 Audi S4 Avant 4 Door Wagon 4.2L 8 Cyl Gas Injected 6 Speed Auto Trans AWD

Exterior Color License VIN

9010 (Black) CA-5LWC422 WAUXL68E55A077180 Unknown

Odometer Production Date Mitchell Service Code

141388 08/2004 910215

Primary Point of Impact Secondary Point(s) of Impact

Right Front Corner (1) Front (12)

Options

Air Conditioning All Wheel Drive Alum/Alloy Wheels AM-FM Stereo Anti-Lock Brake Sys. (ABS)

Auto Air Condition Cassette Player CD Player CD Player (Multi) Cruise Control

Driver Seat With Power Driver-Front Air Bag Dual A/C Electric Defogger Lumbar Support

Fog Lights Front Seats With Power Genuine Wood Trim Heated Mirror

First Row Bucket Seat Fog Lights Front Seats With Lumbar Support High Intensity Discharge Keyless Entry System Leather Seats

Keyless Entry System Leather Seats Leather Steering Wheel Left-Curtain Air Bag

Headlights
Passenger-Front Air Bag Power Door Locks Power Driver Seat Power Passenger Seat Power Remote Mirror

Power Steering Power Windows Premium Sound Sys. Rear Bench Seat Second Row Side Airbag With

Head Protection

Side Airbags Theft Deterrent Sys. Tilt Steering Wheel Traction Control/Electronic Trip Computer

ANDREW SHARP 2005 Audi S4 Avant

Electronic Stability Control

CARS - Nor Cal - Gilroy_1 5.0

| | | | | – LABOR | | | | — PART — | | | |
|--------------|-------------|---------------------------------------|----------------|-----------|----------------|------|----------|----------------------|-----|----------------|-----|
| Line# | | Description | Operation | Туре | Total Units | CEG | Туре | Number | Qty | Total Price | Tax |
| Front Bumper | | | | | | | | | | | |
| 1 | 001001 | Frt Bumper Assy | Remove/Install | Body | 1.4# | 1.4 | Existing | | | | |
| 2 | 002533 | Frt Bumper Cover | Repair | Body | 1.0#* | 2.6 | Existing | | | | |
| 3 | AUTO | Frt Bumper Cover | Refinish Only | Refinish | 1.9 C | 1.9 | Existing | | | | |
| 4 | 900500 | Basecoat Reduction @ Frt Bumper | Refinish Only | Refinish* | -0.3* | 0.0 | Existing | | | | |
| 5 | 003791 | Frt Bumper Spoiler | Remove/Install | Body | 0.4# | 0.4 | Existing | | | | |
| 6 | 002539 | Frt Bumper License Plate Bracket | Remove/Install | Body | 0.2 | 0.2 | Existing | | | | |
| Front I | Lamps | | | | | | | | | | |
| 7 | 000021 | R Frt Combination Lamp Assembly | Remove/Replace | Body | 0.6 | 0.6 | New | 8E0 941 030 F | 1 | \$410.00 | Yes |
| 8 | AUTO | Headlamps | Check/Adjust | Body | 0.4 | 0.4 | | | | | |
| Hood | | | | | | | | | | | |
| 9 | 000083 | Hood Panel | Repair | Body | 2.0#* | 1.5 | Existing | | | | |
| 10 | AUTO | Hood Outside | Refinish Only | Refinish | 2.6 C | 2.6 | Existing | | | | |
| 11 | 900500 | Basecoat Reduction @ Hood | Refinish Only | Refinish* | -0.3* | 0.0 | Existing | | | | |
| Winds | hield | | | | | | | | | | |
| 12 | 000539 | R W/Shield Reveal Moulding | Remove/Replace | Body | 0.3 | 0.3 | New | 8E0 854 328 E 01C | 1 | \$54.00 | Yes |
| Rocker | r / Pillars | | | | | | | | | | |
| 13 | 000646 | R Cowl/Dash Hinge Pillar -S | Repair | Body | 0.3* | 2.5 | Existing | | | | |
| 14 | 900501 | Polish transfer marks | | | | | | | | | |
| 15 | 001575 | R Frt Otr Sill Panel | Remove/Install | Body | 0.4 | 0.4 | Existing | | | | |
| Front [| Door | | | | | | | | | | |
| 16 | 001820 | R Frt Door Shell | Repair | Body | 1.0#* | 6.0 | Existing | | | | |
| 17 | AUTO | R Frt Door Outside | Refinish Only | Refinish | 2.0 C | 2.2 | Existing | | | | |
| 18 | 001830 | R Frt Rear View Mirror | Remove/Install | Body | 0.4# | 0.4 | Existing | | | | |
| 19 | AUTO | R Frt Door Window Frame | Remove/Install | Body | INC# | 2.0 | | | | | |
| 20 | 002941 | R Frt Otr Door Belt Moulding | Remove/Install | • | 2.3# | 2.3 | Existing | | | | |
| 21 | 001864 | R Frt Door Trim Panel | Remove/Install | - | INC | 0.5 | Existing | | | | |
| 22 | 001924 | R Frt Door Handle | Remove/Install | • | 0.5# | 2.5 | Existing | | | | |
| 23 | 900500 | Basecoat Reduction @ Rt Front Door | Refinish Only | Refinish* | -0.3* | 0.0 | Existing | | | | |
| Rear D | | | | | | | | | | | |
| | 002001 | R Rear Door Shell | Repair | Body | 1.0#* | 5.5 | Existing | | | | |
| | AUTO | R Rear Door Outside | Refinish Only | Refinish | 1.6 C | 2.0 | Existing | | | | |
| 26 | 002943 | R Rear Otr Door Belt Moulding | Remove/Install | Body | 2.3# | 2.3 | Existing | | | | |
| 27 | 002015 | R Rear Door Trim Panel | Remove/Install | • | INC | 0.5 | Existing | | | | |
| | 002069 | R Rear Door Handle | Remove/Install | Body | 0.5# | 2.5 | Existing | | | | |
| 29 | 900500 | Basecoat Reduction @ Rt Rear Door | Refinish Only | Refinish* | -0.3* | 0.0 | Existing | | | | |
| Roof | | | | | | | | | | | |
| 30 | 002159 | R Roof Luggage Rack Side Rail | Remove/Install | Body | 0.4 | 0.4 | Existing | | | | |
| 31 | 002160 | L Roof Luggage Rack Side Rail | Remove/Install | Body | 0.4 | 0.4 | Existing | | | | |
| 32 | 000675 | Roof Panel | Repair | Body | 2.0#* | 23.0 | Existing | | | | |

| | | | LABOR | . —— | | - | — PART — | | | |
|------------------------------|---------------------------|-------------------------|-------------------------|----------------|-----|--------------------|----------------------|-----|----------------|-----|
| Line# | Description | Operation | Туре | Total Units | CEG | Туре | Number | Qty | Total Price | Tax |
| 33 AUTO | Roof Panel Outside | Refinish Only | Refinish | 3.0 C | 3.2 | Existing | | | | |
| 34 900500 | Basecoat Reduction @ Roof | Refinish Only | Refinish* | -0.3* | 0.0 | Existing | | | | |
| Sunroof | | | | | | | | | | |
| 35 002166 | Sunroof Assy | Remove/Install | Body | 1.5 | 1.5 | Existing | | | | |
| Additional Costs & Materials | | | | | | | | | | |
| 36 AUTO | Paint/Materials | Additional Cost | | | | | | | \$451.40* | Yes |
| Additional Operations | | | | | | | | | | |
| 37 AUTO | Clear Coat | Additional Operation | Refinish | 2.6 | 0.0 | | | | \$0.00 | |
| Special / Manual Entry | | | | | | | | | | |
| 38 900500 | Cover Car for Overspray | Remove/Replace | e Body* | 0.0* | 0.0 | Aftermarket New | ** Qual Repl Part | 1 | \$10.00* | Yes |

^{*} Judgment Item

C Included in Clear Coat Calculation

T Included in Two Tone Calculation

A Included in Clear Coat and Two Tone Calculation

r CEG R&R Time Used for this Labor Operation

Estimate Totals

| Estillate rotals | | | | |
|-------------------------------|-------|------------|---------------------|--------------------------|
| Labor | Units | Rate | Sublet Add'l Amount | Totals |
| Body Labor | 19.3 | \$81.00 | | \$1,563.30 |
| Refinish Labor | 12.2 | \$81.00 | | \$988.20 |
| Total Labor | 31.5 | | | \$2,551.50 |
| | | | Taxabl | e \$0.00 |
| | | | Тах (0. | 000)% \$0.00 |
| | | | Non-Ta | axable \$2,551.50 |
| | | | Labor | Total \$2,551.50 |
| Parts | | Amount | | |
| Taxable Parts | | \$474.00 | | \$474.00 |
| | | | Parts A | Adjustments -\$23.20 |
| | | | Тах (9. | 000)% \$40.57 |
| | | | Non-Ta | axable \$0.00 |
| | | | Parts | Total \$491.37 |
| Costs | | Amount | | |
| Other Additional Costs | | \$0.00 | | \$0.00 |
| Paint Materials | | \$451.40 | | \$451.40 |
| | | | Taxabl | e \$451.40 |
| Paint Materials Rate: \$37.00 | | | Tax (9. | 000)% \$40.63 |
| Rate Max: 99.9 units | | | Non-Ta | axable \$0.00 |
| Additional Rate: \$0.00 | | | Costs | Total \$492.03 |
| Gross Totals | | Amount | | |
| Gross Total | | \$3,534.90 | | \$3,534.90 |
| | | | Taxabl | e \$902.20 |
| | | | Тах | \$81.20 |
| | | | Non-Ta | axable \$2,551.50 |
| | | | Gross | Total \$3,534.90 |
| Adjustments | | Amount | | |
| Deductible | | -\$100.00 | | -\$100.00 |
| Customer Responsibility | | -\$100.00 | | -\$100.00 |

[#] Labor Note Applies

d Discontinued by Manufacturer

Estimate Totals

Net Estimate Total

\$3,434.90

PURSUANT TO CALIFORNIA CODE OF REGULATIONS, TITLE 10, CHAPTER 5,

SUBCHAPTER 7.5, SECTION 2695.8 THE INSURER WARRANTS THAT ANY

NON-ORIGINAL EQUIPMENT MANUFACTURER PARTS SPECIFIED IN THIS ESTIMATE

ARE AT LEAST EQUAL TO THE ORIGINAL EQUIPMENT MANUFACTURER PARTS IN

TERM OF KIND, QUALITY, SAFETY, FIT AND PERFORMANCE.

**********Inspection Summary Information*******************
Vehicle arrival date?
Was vehicle driven in, towed in or delivered by Road America?

Inspection date?

Number of business days to repair?

Was the estimate given to the owner?

Is the vehicle a partial loss or a total loss?

Is there a Child Safety Seat in the vehicle?

How many if more than one?

Is there damage to the seat(s)?

Name and model of Child Safety seat manufacturer?

Were alternate parts available?

low blue book:

Ikq/alternate parts available -

source-

reference-

phone#

Estimate Event Log

Job Created 2/6/2020 03:36 PM
Estimate Started 2/7/2020 04:48 PM
Estimate Printed 2/7/2020 05:05 PM
Estimate Committed Estimate Not Committed